

- INSPECTION AND MAINTENANCE GUIDELINES:

  INSPECTION SHOULD BE MADE WEEKLY AND AFTER EACH RAINFALL. CHECK THE EMBANKMENT, SPILLWAYS, AND OUTLET FOR EROSION DAMAGE, AND INSPECT THE EMBANKMENT FOR PIPING AND SETTLEMENT. REPAIRS SHOULD BE MADE PROMPTLY AS NEEDED BY THE CONTRACTOR.

  TRASH AND OTHER DEBRIS SHOULD BE REMOVED AFTER EACH RAINFALL TO PREVENT CLOGGING OF THE OUTLET
- ACCUMULATED SILT SHOULD BE REMOVED AND THE BASIN SHOULD BE RE-GRADED TO ITS ORIGINAL DIMENSIONS AT SUCH POINT THAT THE CAPACITY OF THE IMPOUNDMENT HAS BEEN REDUCED TO 1/2 OF ITS ORIGINAL STORAGE
- THE REMOVED SEDIMENT SHOULD BE STOCKPILED OR REDISTRIBUTED IN AREAS THAT ARE PROTECTED FROM EROSION.



## CITY OF HUTTO

CONSTRUCTION STANDARDS AND DETAILS

SEDIMENT BASIN **BAFFLE** 

ENGINEERING & PUBLIC WORKS

DRAWING N	O. ESC08
UPDATED:	02/01/2019
DRAWN BY:	ВВ
SCALE:	N.T.S.
FILE NAME:	ESC08.DWG